# 



Plan for two to four extra seals in parts inventory

#### PREVENTATIVE MAINTENANCE GASKETS

Be sure to have enough footage for one or two replacements

#### LONG LEAD TIME **AGITATORS**


Having a spare agitator will help avoid uneccessary downtime

#### RECOMMENDED SPARES **BEARINGS**

Mepaco's recommendation for bearings is one or two backups.

#### **RECOMMENDED SPARES** SAFETY SWITCHES

Safety switches are at risk for damage by personnel; keep an ample supply



#### LONG LEAD TIME **CYLINDERS**

Be sure to have backups that support your usage

## **EMERGENCY**

Mepaco recommends you have a spare motor in the event of an emergency

### 7 PARTS TO CONSIDER FOR PLANNED SHUT-DOWN

www.mepaco.net

(920) 356-9900